

Picture 2: *Zoomed in on ATS 500XM scope recording of TCV vs Pump shaft sensor when the engine is misfiring badly.*

Click here *for more information about scopes.*