



Picture 3: *ATS 500XM scope recording, Ch2 connected to injector #4 (faulty) power supply, and Ch1 connected to the injector current control wire.*

[Click here](#) for more information about scopes & Scan tools