Picture 1: ATS 5004d recording of the crankshaft sensor, Injection and the coils on cylinder 3 and 4.

FiePie Multi Channel - H:\Mijn documenten\MTA artikelen\2015\okt\00091_00_2capign.tps