Picture 2: Recording of the crankshaft sensor, Injection and the coils on cylinder 3 and 4 zoomed in.