



Picture 3: ATS scope recording of TCV voltage over current, running good (cold engine).

[Click here](#) for more information about scopes.