

Picture 4: TCV voltage over current, running really bad (warm engine).